

**APPENDIX B:  
PHOTOS OF THE PROJECT SITE**

# 2016 Photographs from Pioneer Environmental Services, Inc.



Photo 1: Looking West along proposed pathway route. (Pioneer 2016)



Photo 2: Looking East along proposed pathway route. (Pioneer 2016)



Photo 3: Looking East along proposed pathway route. (Pioneer 2016)



Photo 4: Looking West along proposed pathway route. (Pioneer 2016)



Photo 5: Looking South along Spring Gulch. (Pioneer 2016)



Photo 6: Looking West at Scrub-Shrub wetlands along proposed pathway route. (Pioneer 2016)



Photo 7: Looking West at Scrub-Shrub wetlands along proposed pathway route. (Pioneer 2016)



Photo 8: Looking West at Scrub-Shrub wetlands along proposed pathway route. (Pioneer 2016)



Photo 9: Looking West along proposed pathway route in Scrub-Shrub wetland area. (Pioneer 2016)



Photo 10: Looking West into Scrub-Shrub wetland area along proposed pathway route. (Pioneer 2016)

## 2013 Photographs from Alder Environmental



**PHOTO 1:** Spring Gulch looking southwest



**PHOTO 2:** Spring Gulch looking southeast



**PHOTO 3:** Spring Gulch sample point SP1



**PHOTO 4:** Spring Gulch sample point SP1 soil profile



**PHOTO 5:** Spring Gulch sample point SP2



**PHOTO 6:** Spring Gulch sample point SP2 soil profile



**PHOTO 7:** Spring Gulch sample point SP3



**PHOTO 8:** Spring Gulch sample point SP3 soil profile



**PHOTO 9:** Spring Gulch sample point SP4



**PHOTO 10:** Spring Gulch sample point SP4 soil profile

## 2016 Photographs from Alder Environmental



**Photo Number: 1**

Date Taken: 03/05/2015

Description: Scrub-shrub wetland along fence line. Photo to east along HWY 22.



**Photo Number: 2**

Date Taken: 03/05/2015

Description: Spring Creek Ditch water flowing south under HWY 22. Photo to the Northeast.



**Photo Number: 3**

Date Taken: 03/05/2015

Description: Spring Creek flowing under HWY 22 surrounded by scrub-shrub wetlands. Photo to east.



**Photo Number: 4**

Date Taken: 03/05/2015

Description: Scrub-shrub wetland boundary along HWY 22. Photo to east.



**Photo Number: 5**

Date Taken: 03/05/2015

Description: Scrub-shrub wetland boundary along HWY 22. Photo to east.



**Photo Number: 6**

Date Taken: 10/13/2011

Description: SP-1  
Scrub-shrub wetland



**Photo Number: 7**

Date Taken: 10/13/2011

Description: SP-1  
Scrub-shrub wetland



**Photo Number: 8**

Date Taken: 10/13/2011

Description: SP-2  
Upland



**Photo Number: 9**

Date Taken: 10/13/2011

Description: SP-2  
Upland



**Photo Number: 10**

Date Taken: 10/13/2011

Description: SP-3

Scrub-shrub wetland



**Photo Number: 11**

Date Taken: 10/13/2011

Description: SP-3

Scrub-shrub wetland



**Photo Number: 12**

Date Taken: 10/13/2011

Description: SP-4

Upland



**Photo Number: 13**

Date Taken: 10/13/2011

Description: SP-4

Upland



**Photo Number: 14**

Date Taken: 3/10/2016

Description: SP-5

Scrub-shrub wetland



**Photo Number: 15**

Date Taken: 3/10/2016

Description: SP-5

Scrub-shrub wetland



**Photo Number: 16**

Date Taken: 3/10/2016

Description: SP-6

Upland



**Photo Number: 17**

Date Taken: 3/10/2016

Description: SP-6

Upland



**Photo Number: 18**

Date Taken: 3/10/2016

Description: SP-7

Scrub-shrub wetland



**Photo Number: 19**

Date Taken: 3/10/2016

Description: SP-7  
Scrub-shrub wetland



**Photo Number: 20**

Date Taken: 3/10/2016

Description: Stephen Adams Ditch at  
culvert outlet south side of highway.  
Concrete headgate structure leads  
west.



**Photo Number: 21**

Date Taken: 7/20/2015

Description: Pathway being  
constructed at Spring Gulch Road  
intersection. Silt fence running along  
wetland boundary. Wetlands have  
not changed since 2011 delineation.