


Attachment 1
Location and topography of the Path 22 West
project area, Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 2,000 feet

LEGEND

-  Proposed Pathway Project Area
-  Platted Parcels



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002



Attachment 2
 2011 aerial photograph depicting alignment and
 land ownership of the Path 22 West project area,
 Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 300 feet
 2011 Aerial Photography


LEGEND

- Proposed Pathway Limits of Disturbance
- Platted Parcels

research & consulting inc.



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002



Attachment 3
 2011 aerial photograph depicting surface water
 features within the Path 22 West project area,
 Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 300 feet
 2011 Aerial Photography

LEGEND

- Proposed Pathway Limits of Disturbance
- Surface Water Features
- Protected River Setback (150 ft)
- Platted Parcels

research & consulting inc.

Biota



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002

Attachment 4
 2011 aerial photograph depicting delineated
 wetlands within the Path 22 West project area,
 Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 300 feet
 2011 Aerial Photography

LEGEND

-  Proposed Pathway Limits of Disturbance
-  Wetlands
-  Wetland Impacts
-  Wetland Impact Areas
-  Platted Parcels



research & consulting inc.

Biota



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002

Attachment 5
 2011 aerial photograph depicting delineated wetlands and wetland impacts within the western portion of the Path 22 West project area, Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 160 feet
 2011 Aerial Photography

LEGEND

-  Proposed Pathway Limits of Disturbance
-  Wetlands
-  Wetland Impacts
-  Wetland Impact Areas
-  Platted Parcels



research & consulting inc.



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002

Attachment 6
 2011 aerial photograph depicting delineated
 wetlands and wetland impacts within the eastern
 portion of the Path 22 West project area,
 Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 160 feet
 2011 Aerial Photography

LEGEND

-  Proposed Pathway Limits of Disturbance
-  Wetlands
-  Wetland Impacts
-  Wetland Impact Areas
-  Platted Parcels



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002

Rendezvous Lands Conservancy Lot




Attachment 7
1945 aerial photograph depicting 2011 delineated wetlands and wetland impacts within the eastern portion of the Path 22 West project area, Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 160 feet
1945 Aerial Photography

LEGEND


-  Proposed Pathway Limits of Disturbance
-  Wetlands
-  Wetland Impacts
-  Wetland Impact Areas
-  Platted Parcels



research & consulting inc.



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002



Attachment 8
 Aerial photograph depicting vegetative
 covertypes within the Path 22 West project
 area, Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 300 feet
 2011 Aerial Photography


LEGEND

-  Proposed Pathway Limits of Disturbance
-  Scrub-Shrub Wetlands
-  Forested Wetlands
-  Mesic Tall Shrub
-  Mesic Cottonwood (Medium-aged)
-  Mesic Cottonwood (Mature)
-  Disturbed
-  Open Water

research & consulting inc.



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002
 PO Box 880, Victor, ID 83455



Attachment 9
 Aerial photograph depicting vegetative
 covertypes within the western portion of the
 Path 22 West project area,
 Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 140 feet
 2011 Aerial Photography

LEGEND

-  Proposed Pathway Limits of Disturbance
-  Scrub-Shrub Wetlands
-  Forested Wetlands
-  Mesic Tall Shrub
-  Mesic Cottonwood (Medium-aged)
-  Mesic Cottonwood (Mature)
-  Disturbed
-  Open Water

research & consulting inc.



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002
 PO Box 880, Victor, ID 83455



Attachment 10
 Aerial photograph depicting vegetative
 covertypes within the eastern portion of the
 Path 22 West project area,
 Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 120 feet
 2011 Aerial Photography

LEGEND


-  Proposed Pathway Limits of Disturbance
-  Scrub-Shrub Wetlands
-  Forested Wetlands
-  Mesic Tall Shrub
-  Mesic Cottonwood (Medium-aged)
-  Mesic Cottonwood (Mature)
-  Disturbed
-  Open Water

research & consulting inc.

Biota



PO Box 8578, 140 E. Broadway, Suite 23, Jackson, WY 83002
 PO Box 880, Victor, ID 83455



Attachment 11
2011 aerial photograph depicting crucial moose
winter yearlong range within and in the vicinity of
the Path 22 West project area,
Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 800 feet
2011 Aerial Photography

LEGEND

-  Proposed Pathway Limits of Disturbance
-  Crucial Moose Winter Yearlong Range
-  Platted Parcels



Attachment 9
Location of bald eagle nests and their
associated 660-foot setback in the vicinity
of the Path 22 West project area,
Teton County, Wyoming.

February 14, 2013

Approximate Scale: 1 inch = 2,000 feet

LEGEND

-  Project Area
-  Bald Eagle Nests
-  Nest Setback (660 ft)

